

#### Republic of the Philippines

#### Department of Education

**REGION X** 

#### SCHOOLS DIVISION OF CAGAYAN DE ORO CITY

Office of the Schools Division Superintendent

December 9, 2018 AGAYAN DE ORO CITY

RELEASE DEC 12

DIVISION MEMORANDUM No. 1002 s. 2019

#### SEMINAR-WORKSHOP ON NATIONAL SCHOOL BUILDING INVENTORY (NSBI) - PHASE 1 FOR SY 2019-2020

To: Public Schools District Supervisors
Public Elementary and Secondary Schools Heads
School Property Custodians/Physical Facilities Coordinators
This Division

- In line with the conduct of the National School Building Inventory, the Planning and Research Section and Education Facilities Section will conduct a Seminar-Workshop on National School Building Inventory (NSBI) for SY 2019-2020 on December 19, 2019. The venue will be announced in a separate issuance.
- 2. The activity aims to orient the participants on the following:
  - a. NSBI Forms, system, policies and standards.
  - b. Capacitate the school personnel in the conduct of National School Building Inventory of DepEd Public School Buildings.
  - c. Provide an updated and more accurate and comprehensive baseline data of school buildings in all DepEd public schools for use in planning, budgeting and decision making.
- 3. The participants of the seminar-workshop include One (1) School Head/School In-charge and One (1) School Property Custodian or Physical Facilities Coordinator of all Public Elementary and Secondary Schools. The following are the schedules and the required participants.

Date	Participants	Total Pax
	Elementary School Heads/In-charge and School Property Custodian/Physical	150
December 19, 2019	Facilities Coordinators	
	Secondary School Heads/In-charge and	
	School Property Custodian/Physical	88
	Facilities Coordinators	
	NSBI Technical Working Group	6



Address: Fr. William F. Masterson Ave., Upper Balulang, Cagayan de Oro City

Telephone No: (08822)855-0048 Website: www.depedcdo.net

Email: cagayandeoro.city@deped.gov.ph



#### Republic of the Philippines

#### Department of Education

#### **REGION X**

#### SCHOOLS DIVISION OF CAGAYAN DE ORO CITY

- 4. Participants must bring the following:
  - a. Print copy of Enclosure A Revised Templates for National School Building Inventory 2019
  - b. National School Building Inventory SY 2016 Report with Site Development Plan
  - c. Certifications from Municipal Building Office for condemned buildings
- 5. Travelling expenses and other incidental expenses incurred by the participants relative to the seminar-workshop shall be charged against School MOOE and local funds subject to the usual auditing rules and regulations.
- 6. Participants are expected to come on time. The opening program will start at 8:00 o'clock in the morning. Only lunch and snacks will be served.
- 7. Enclosed herewith are the revised NSBI Templates.
- 8. Immediate dissemination and strict compliance of this Memorandum is desired.

CHERRY MAE L. LIMBACO Schools Division Superintendent

Encls.: As stated



Address: Fr. William F. Masterson Ave., Upper Balulang, Cagayan de Oro City

Telephone No: (08822)855-0048 Website: www.depedcdo.net

Email: cagayandeoro.city@deped.gov.ph



×	School ID:
CAGAYAN DE ORO CITY	School Name :

Table 1. Summary of Existing Building/Structure

Prepared by:								Col. 1	Building/ Structure Number <sup>1</sup>
								Col. 2	Building/Structure Type <sup>2</sup>
								Col.3	Fund Source/s <sup>3</sup>
								Col. 4	Specific Fund Source/s <sup>4</sup>
								Col. 5	Building/Structure Condition <sup>5</sup>
Certified True and Correct by:								Cot 6	Number of Storeys <sup>6</sup>
Correct by:					Annual States			Cot. 7	Number of Rooms
								Cot. 8	Year Completed <sup>9</sup> (If not provided, refer to building type)
					gelacific men en general de la contraction de la			Cot 9	Classification of Building/Structure <sup>9</sup>
Validated by:								Col. 10	Is building PWD accessible? <sup>10</sup> (Yes/No)
								Cot. 11	Have undergone major repair for the last 5 years <sup>11</sup> (Yes/No)
								Col. 12	With Certificate of Acceptance <sup>12</sup> (Yes/No)
								Col. 13	Is the school building Included in the DepEd Book of Accounts? (Yes/No)

School Property Custodian/ School Engineering Facilities Coordinator

School Head

ENGR. ELY V. MAMACLAY II
Schools Division Office



Region:	School ID:	
Division :	School Name :	

#### Table 2. Existing Rooms per Building

Building/	13	14	, 15	Room	Dimension Meters) <sup>16</sup>
Structure Number <sup>1</sup>	Room Number <sup>13</sup>	Room Condition <sup>14</sup>	Actual Usage/s <sup>15</sup>	Width	Length
Col. 1	Col. 2	Col. 3	Col. 4	Col. 5	Col. 6
		and the same production of the same same same same same same same sam	and the second s		
					Maria Cara Cara Cara Cara Cara Cara Cara
elementer et en	in all an independent of the second				
pared by:			Certified true and correct by:	V	alidated by:
pared by:			Certified true and correct by:	V	alidated by:

Prepared by:	Certified true and correct by:	Validated by:
		ENGR. ELY V. MAMACLAY II
School Property Custodian/	School Head	Schools Division Office



# School Building Inventory Form Department of Education (as of October 31, 2019)

Region:	School ID:
Division:	School Name:

# Table 3. Existing Number of Water and Sanitation Facilities

nter	E .	T			
Stand alone Water	and Santiation Facility <sup>24</sup>	Col. 13			
	Without Water Supply	Col. 12			
Number of Faucets <sup>23</sup>	With Without Water Supply	Col. 11			
With	Septic Tank <sup>22</sup> (Yes/No)	Col 10			
Some	Urinal Trough <sup>21</sup>	Cof. 9			
Wumborof	The same of the sa	Col. 8			
Number of	Sink/ Washbasin <sup>19</sup>	Cof. 7			
Number of	Non-Functional Toilet Bowls <sup>18</sup>	Col. 6			
wls <sup>17</sup>	Shared	Col. 5			
Number of Functional Toilet Bowls <sup>17</sup>	PWD	Col. 4			
	Female	Col. 3			
Numi	Male	Col. 2			
Building/	Structure Number <sup>1</sup>	Col. 1			

Prepared by:

Certified True and Correct by:

School Head

Validated by:

ENGR. ELY V. MAMACLAY II Schools Division Office

School Property Custodian/ School Engineering Facilities Coordinator



Region:	School ID	):
Division:	School Na	ame:

#### Table 4. Existing Number of Usable Furnitures

Building/ Structure Number <sup>1</sup>	Kinder Modular Table <sup>25</sup>	Kinder Chair <sup>26</sup>	Arm Chair <sup>27</sup>	School Desk <sup>28</sup>	Other Classroom Table <sup>29</sup>	Other Classroom Chair <sup>30</sup>	DepEd New Design 2-Seater Table & Chair <sup>31</sup>
Col. 1	Col. 2	Col. 3	Col. 4	Col. 5	Col. 6	Col. 7	Col. 8
	Address and the last of the la						The second secon
		ALL CONTRACTOR OF THE PARTY OF					
	ļ.,,,						
				- Arthur and Arthur an			
			COLUMN TO THE PARTY OF THE PART			-	

School Property Custodian/ School Engineering Facilities Coordinator	School Head	ELY V. MAMACLAY II Schools Division Office		
Prepared by:	Certified true & Correct	Validated by:		



Region:	School ID:						
Division:	School Name:						
Table 5. Other Facilities							
Other Facilities	Pr	resent in Campus? (Yes/No)					
Col. 1		Col. 2					
Covered Court	O Yes	O No					
Gymnasium	O Yes	O No					
Entrance Gate	O Yes	O No					
Permanent Perimeter Fence	O Yes	O No					
Temporary Perimeter Fence	O Yes	O No					
Playground	O Yes	O No					
School Garden	O Yes	O No					
Solar Panel	O Yes	O No					
Prepared by:	Certified Tr	ue and Correct by:					
School Property Custodian/ School Engineering Facilities		School Head					

ENGR. ELY V. MAMACLAY II
Schools Division Office

Validated by:



#### **ANSWERING GUIDE**

#### Table 1. Summary of Existing Building/Structure

<sup>1</sup> Building/Structure Number

<sup>2</sup> Building/Structure Type

Refers to the number of the building /structure based on the site development plan.

Refers to the different design of school buildings and structure

within the school site.

Deped National Funded Building Types	Start of Implementation		
Academic Classroom Buildings			
Army Type School Building	1957		
Bagong Lipunan School Building (BLSB) Type I	1975		
Bagong Lipunan School Building (BLSB) Type II			
Bagong Lipunan School Building (BKSB) Type III	1975		
DepED Modified School Building (7 x 7)	2006		
DepED Standard School Building	2005		
DPWH-BOD School Building			
FVR 2000 Building	2000		
Gabaldon School Building	1920		
	2005		
Home Economics Building	1983		
Imelda Type school Building	The first control of the state		
Industrial Arts Building	2005		
Learning and Public Use School (LAPUS) Building	2007		
Magsaysay Type	1950		
Marcos Pre-Fabricated School Building	1970		
(Marcos Type)			
Multi-Purpose Workshop Building	2006		
Pre-School/Kindergarten Building	2011		
Public-Private School Infrastructure Project	2013		
(PSIP School Building)	AU LU		
Readily Assembled Multi-Option Shelter			
(RAMOS) Type			
Science Laboratory Building	2006		
Public-Private Partnership (PPP)			
Ramos Demountable School Building			
Pre-FAB			
Technical Vocational School Buildings			
Aqua-Culture NC II Building	2013		
Automotive Servicing NCII Building	2013		
Beauty Care NC II Building	2013		
Carpentry NC II Building	2013		
Commercial Cooking NC II Building	2013		
Consumer Electronic Technician NC II Building	2013		
Dress Making NC II Building	2013		
Electrical Installation Maintenance NC II Building	2013 2013		
Food Processing NC II Building	2013		
Shielded Metal Arc Welding NC II Building State of the Art Tech Voc Bldg	2015		



#### ANSWERING GUIDE

ANDITAL	
LGU Funded Building Types	
Joson Type	
Ynares Type	
Provincial School Board	
Municipal Building	and an analysis of the state of
Espino Building	
UMALI Building	
Tulagan Building	
Violago Type	
Gonzales Type	THE RESIDENCE OF THE PROPERTY
Joey Lina Building	
Lazaro Building	
Agbayani Bldg.	
Celeste Building	The state of the s
Rodriguez Building	A SECOND STATE OF THE SECO
Alfelor Type	
Estrella	
Mandanas Building	
Montelibano Type	
San Luis Building	
Deloso Type Building	
Maliksi Building	
Lajara Type Building	ABBUILD MAINTAINE THE THE STORE OF THE STORE
Gatuslao Building	AND THE RESIDENCE OF THE PROPERTY OF THE PROPE
Luna Building	
Dy Building	AND THE RESERVE OF THE PROPERTY OF THE PROPERT
Espino	
Gwen Bldg.	
Mathay Building	
Agbayani Type	A STATE OF THE STA
Duque Building	
Gustilo Type	
Others	
Ottle13	
Foreign Funded Building Types	Start of Implementation
Economic Support Fund (ESF) School Building	1985
ICA - Educational Facilities Improvement Program (EFIP)	1994
Government of Spain-Spanish Grant School Building	
BP4BE Building-AusAid	2013
Secondary Education Development Improvement Program	4013
(SEDIP)	
Secondary Education Development Program (SEDP)	2002
SPHERE Building - Ausaid	2002
Third Elementary Education Projecy(TEEP) Schiool Building	1999-2006
ICA - Typhoon Resistant School Building Program (TRSBP)	1988
Others	Control of the Contro



#### ANSWERING GUIDE

Private Sector Funded Building Typ			
Federation of Filipino Chinese Chamber of Co	nmerce and		
Industry, Inc. (FFCCCII) School Build			
Little Red School House - Coca-Cola Phili	piines		
ABS- CBN School Building			
<b>GMA Kapuso School Building</b>			
Private Foundation Building			
Security Bank School Building			
Petron School Building			
Plan International School Building			
AGAPSchool Building			
Aboltiz School Building			
PAMANA School Building			
RPN School Building			
Rotary School Building			
Lions Club School Building		OUR DISTRICT SERVICE SERVICES OF THE SERVICE AND ADDRESS OF THE SERVICE SERVICES.	
Jolibee School Building			
Mc Donald School House			
KABISIG School Building			
Gawad-Kalinga School Building			
PLDT Schoolm Building			
SM Foundation School Building			
TZU CHI Foundation School Buildir	g		
Ayala School Building			
JAYCEES School Building			
Philip Morris School Building			
RC Cola Building	A	and the first of the control of the second o	
DMCI School Building			
KIWANIS School Building		NOTES TO CONTROL OF THE PROPERTY OF THE PROPERTY AND THE PROPERTY OF THE PROPE	AMERICAN TO THE OWNER.
SteelTech School Building		wite the first of the party of the transfer of the party	
Others			



#### ANSWERING GUIDE

ouse of Representative/Senate Funded Building Types	
Gonzales Type	
Cojuangco Building	
Úmali	
Maceda	
Chipeco Type Building	
Tanada Building	
Villareal Building	
Ferrer	
Bayan Muna	
Angara Building	
Abaya Type	
Fuentebella Building	
Joson Type Building	
Legarda Building	
Drilon Building	
Enverga Building	
Andaya	
Diaz Type	
Recto Building	
Enrile Building	
Alvarez	
Loren Legarda Building	
Cibac	
Lagman Type	
Romulo	
Serbisyong Suarez Building	
Syjuco Building	
Villareal Bldg.	
Antonino	
Arenas	
Others	
Other National Government Agency Funded	
Building Types	
DOST Science Laboratory Building	
PAGCOR School Building	
KALAHI-CIDSS	
PAG-IBIG	
Others	
STRUCTURE TYPES	
Auditorium	
Brgy. Health Center	
Canteen	
Comport Room	
Covered Walk	
Covered Court	
the state of the s	
Day Care Center	
Guard House	
Gymnasium	
Gazebo	
School Stage	
Washing Facilities	
Others	
	Majorine Anna Marie



ANS	WERING GUIDE
	Refers to the source of budget for construction of buildings and
<sup>3</sup> Fund Source/s	rooms.
DepEd National Funded	Refers to the school building funded by DepEd.
LGU Fuded	Refers to the school building funded by LGUs. (Provincial, City and Municipality)
Foreign Funded	Refers to the school building funded by foreign institution.
Private Sector Funded	Refers to the school building funded by private corporations, companies, individuals and associations.
House of Representative/Senate Funded	Refers to the school building funded through the house of representatives/senate. (CDF, PDAF etc.)
Other National Government Agency Funded	Refers to the school building funded by other government agencies.
Note: If building has multiple fund source, specify in colu	ımn 3.
<sup>4</sup> Specific Fund Source/s	Refers to the specific source of budget for construction of buildings and rooms.
DepEd budget	
Alumini	
JICA Worldbank	
AusAid	
Coca-Cola Philippines	
Others	
Note: If building has multiple specific fund source, specif In column 4 specify only for LGU funded, foreign funded	
<sup>5</sup> Building/Structure Condition	Refers to the current phylscal state of a building/structure.
Good Condition	Refers to a building which does not need repair.
Needs Minor Repair	Refers to the repair or replacement of school building components which are not subjected to critical structural loads and stresses and which are estimated to cost less than ten percer (10%) of the cost of a standard building unit such as repair of windows, doors, partitions and the like.
Needs Major Repair	Refers to the repair or replacement of school building components which are subjected to critical structural loads and stresses and which are estimated to cost ten percent (10%) or more of the cost of a standard building unit such as roof frames, posts and exterior walls.
On-going Construction	Refers to the school building/structure that are not yet complete and/or not yet turned over.  Kerers to a building/structure which was not completed
For Completion	according to the design (e.g. one storey building was completed using a two storey design building plan).
For Condemnation	Refers to the school building/structure that are not safe for occupancy and not currently used but without official declaration from the Municipal/City Engineer.
Condemned/For Demolition	Refers to a building officially declared by the Municipal/City Engineer to be dangerous to the life, health, property or safety of the public or its occupants.
<sup>6</sup> Number of Storeys	Refers to the number of levels/floors in a building/structure.
Number of Rooms by Design/Intent	Refers to the number of rooms by its design/intent.
Transpor of mooning by benignymeene	Refers to the specific year when a building was completed and
<sup>8</sup> Year Completed	officially turned over to the school.
	officially turned over to the school.  Refers to the classification of how the building is constructed.
<sup>8</sup> Year Completed	The second secon
<sup>8</sup> Year Completed <sup>9</sup> Classification of Building/Structure	Refers to the classification of how the building is constructed.



(as of Octo	ber 31, 2019)
ANSWEI	RING GUIDE
<sup>10</sup> Is building PWD accessible? <sup>11</sup> Have undergone major repair for the last 5 years	Refers to buildings that are compliant with the BP No. 344 (Accessibility Law) and the RA No. 7277 (Magna Carta for Disabled Persons) which aims to make all buildings in the country accessible to persons with disabilities (PWDs) Refers to the Building/Structure which underwent repair within the last 5 years.
	connected to owner light. It departs and martly of differ a propin-
<sup>12</sup> With Certificate of Acceptance	Refers to newly constructed school buildings duly accepted by DepEd thru the Principal/School Head by way of signing of the Certificate of Acceptance
Paupris	Refers to a device by which water flows.  Remark of water hand commence (wellow that bounded commence)
13 Is the school building included in the DepEd Book of Accounts	Refers to buildings that were already booked as assets of DepEd following standard accounting procedures for the transfer and booking-up of the subject facilities
Table 2. Existing Rooms per Building	
<sup>12</sup> Room Number	Refers to the number assigned to a room.
<sup>13</sup> Room Condition	Refers to the current physical state of a room.
Good Condition	Refers to a room which does not need repair.
Needs Minor Repair	Refers to the repair or replacement of room components which are not subjected to critical structural loads and stresses and which are estimated to cost less than ten percent (10%) of the cost of a standard room unit such as repair of windows, doors, partitions and the like.
Needs Major Repair	Refers to the repair or replacement of room components which are subjected to critical structural loads and stresses and which are estimated to cost ten percent (10%) or more of the cost of a standard room.
<sup>14</sup> Actual Usage/s	Refers to the manner by which a room is currently being utilized, it should correspond to the number of usages (e.g If the room is shared by two SPED classes held at the same time, actual usage is SPED classroom and SPED classroom).
Instructional	Classroom SPED, Classroom Elementary, Classroom JHS, Classroom SHS, ALS Room, Audio Visual, Computer Room, Industrial Arts Room, Home Economic Room, Science Laboratory, Speech Laboratory, Research Laboratory, Not Currently Used
Non-Instructional	Library/Learning Resource Center, Canteen, Clinic, Conference Room, Offices, Faculty Room, Museum, Supply Room, Conference Room, Data File Room/Records Room, Student Co-Curricular Center, Youth Development Center, Not Currently Used, Others
Combination	Combination of Instructional and Non-Instructional
<sup>15</sup> Room Dimension (in Meters)	Refers to the size of a room specifying the width and length (WxL). Width refers to the side of the chalkboard while length refers to the side of the window.
Table 3. Existing Number of Water and Sanitation Faci	littes
<sup>16</sup> Functional Toilet Bowls	Refers to the serviceable toilet bowls.
Functional Tollet Bowls	Refers to the serviceable tollet dowls.



No principal and an arrangement of the second and t		
ANSWERING GUIDE		
<sup>17</sup> Non-Functional Toilet Bowls	Refers to the non-serviceable toilet bowls.	
<sup>18</sup> Sink/Washbasin	Refers to a sink or washbasin.	
<sup>19</sup> Urinals	Refers to the bowls or other receptacles, typically attached to a wall in a restroom, into which men may urinate.	
<sup>20</sup> Urinal Trough	Refers to a long, narrow open container used for urinating.	
<sup>21</sup> Septic tank	Refers to a sewage-disposal unit used for homes/schools not connected to sewer lines. It consists ordinarily of either a single-or double compartment of concrete buried in the ground, so designed that settled sludge (waste) is in contact with the waste water as it flows through the tank and then to a drain field. Solids are decomposed by the anaerobic bacterial action of the sludge.	
<sup>22</sup> Faucets	Refers to a device by which water flows.	
<sup>23</sup> Stand alone Water and Sanitation Facility	Refers to water and sanitation facilities that houses a certain number of bowls, urinals and faucets and were constructed	

separately from the school buildings



ANSV	VERING GUIDE
Table 4. Existing Number of Usable Furnitures	
<sup>24</sup> Kinder Modular Table	Refers to the standard modular table used by kindergarten learner.
<sup>25</sup> Kinder Chair	Refers to the chair used by kindergarten learner.
<sup>26</sup> Arm Chair	Refers to a usable armchairs in the school, regardless of material (wood, plastic).
<sup>27</sup> School Desk	Refer to usable two-seater desks in the school.
<sup>28</sup> Other Classroom Table	Refers to the table used by learner in the classroom.
<sup>29</sup> Other Classroom Chair	Refers to the chair used by learner in the classroom.
<sup>30</sup> DepEd New Design 2-Seater Table and Chair	Refers to the new design of school furniture of which 1 set is equal to 2 chairs and 1 table on wood and steel finishes
Table 5. Other Facilities	
Covered Court	Refers to an area within the school campus covered by roof and usually supported by steel trusses. It is commonly used for school activities like sports, physical exercises and other activites of the school
Gymnasium	Refers to a room or building within the school equipped for gymnastics, games, and other physical exercises. It is also often used as venue for various indoor school programs and activities and some others even has spectator accomodations (bleachers)
Entrance Gate	Refers to a barrier used as an entrance and exit of the school, which can be closed and locked beyond school hours.
Permanent Perimeter Fence	Refers to a permanent structure used to demarcate the perimeter of the school to prevent access
Temporary Perimeter Fence	Refers to a structure that has the same purpose as a permanent perimeter fence but is temporary in nature and may not be as sturdy as a permanent one
Playground	Refers to an outdoor area specifically provided for learners to play on.
School Garden	Refers to an area used for growing plants.
Solar Panel	Refers to a set/s of panel/s designed to absorb the sun's rays as a source of energy for generating electricity for the school building or other facilities